Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: SANDERS 24-19

Field Name: PRONGHORN Well File #: 11781

Date Incident: 8/26/2016 Time Incident: 19:30 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 101 Sec: 19 Qtr: SW SE

Location Description:

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 20 Barrels 2 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The site is inactive and water came from another well. The faulty parts will be replaced and system isolated to prevent future incidents. Hydrovac and clean up equipment to be mobilized.

Wastes Disposal Location: Water was taken to the Nygaard SWD. Solids to Secure 13 Mile corner.

Agencies Involved:

Updates

Date: 8/29/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC retains oversight.